


Current layout



Long queues on M62 approach

The interchange reaches capacity at peak times


Queues often form at the traffic lights, leading to traffic queuing back from this point

The interchange was built in the 1960s and now needs regular maintenance

Diagrammatic representation only

© Crown copyright and database rights 2021 OS 100030649 LEE21_0048

Option A






Roundabout to be replaced

New slip-road

New drainage pond

New roundabout with additional lanes

-  Demolish existing roundabout
-  Proposed improvements
-  New embankments

Diagrammatic representation only
© Crown copyright and database rights 2021 OS 100030649
LEE21_0048

Option B



New free-flow link

New drainage pond




New drainage pond

- Proposed improvements
- New embankments

Diagrammatic representation only
© Crown copyright and database rights 2021 OS 100030649
LEE21_0048

Option C



-  Demolish existing roundabout
-  Proposed improvements
-  New embankments

Diagrammatic representation only

© Crown copyright and database rights 2021 OS 100030649
LEE21_0048